


40



F19.2

START LE 300

Forming sate insulator 5302

Forming 1st metal barrier 504

Somming 2nd metal gate obstrale 1

Fg. 3